

序号	报告编号	发布日期	结论	影像资料
43	GX-B1380/20-6-24001	2024/3/20	所检项目合格。	 A worker in a red helmet and blue jacket is kneeling on a metal platform inside a tunnel, measuring a horizontal distance with a tape measure. The tunnel walls are lined with wooden planks, and there are some pipes and equipment visible in the background. The timestamp "2024 03 03" is visible in the bottom right corner of the image.
44	GX-B1380/20-6-24002	2024/3/20	所检项目合格。	 A worker in a red helmet and blue jacket is standing on a metal platform inside a tunnel, measuring a horizontal distance with a tape measure. The tunnel walls are lined with wooden planks, and there are some pipes and equipment visible in the background. The timestamp "2024 03 03" is visible in the bottom right corner of the image.

45	GX-B1380/20-6-24003	2024/3/20	所检项目合格。	
46	GX-B1380/20-6-24004	2024/3/20	所检项目合格。	
47	GX-B1380/20-6-24005	2024/3/20	所检项目合格。	

48	GX-B1380/20-6-24006	2024/3/20	所检项目合格。	 2024 03 04
49	GX-B1304/21-6-24001	2024/3/20	所检项目合格。	 2023 09 15
50	GX-B1520/20-6-24023	2024/3/21	综合判定：合格。	 2024 03 21


51	GX-B1520/20-6-24019	2024/3/15	综合判定合格	
52	GX-B1520/20-6-24020	2024/3/15	综合判定合格	
53	GX-B1328/20-6-24036	2024/3/15	所检项目合格	

54	GX-B1307/20-6-24006	2024/3/14	综合判定合格	
55	GX-B1304/21-6-24003	2024/3/19	综合判定：合格。	
56	GX-B1304/21-6-24002	2024/3/19	综合判定：合格。	

57	GX-B1303/21-6-24005	2024/3/19	综合判定：合格。	
58	GX-B1303/21-6-24006	2024/3/19	综合判定：合格。	
59	GX-B1303/21-6-24007	2024/3/19	综合判定：合格。	

60	GX-B1428/21-6-24003	2024/3/21	无缺陷迹痕显示	
61	GX-B1304/21-6-24003	2024/3/19	综合判定：合格。	
62	GX-B1304/21-6-24002	2024/3/19	综合判定：合格。	

63	GX-B1303/21-6-24005	2024/3/19	综合判定：合格。	
64	GX-B1303/21-6-24006	2024/3/19	综合判定：合格。	
65	GX-B1303/21-6-24007	2024/3/19	综合判定：合格。	

66	GX-B1428/21-6-24003	2024/3/21	无缺陷迹痕显示			
67	GX-B1322/21-6-24013~24024	2024/3/20	所检项目合格			
68	GX-B1309/21-6-24001	2024/3/20	所检项目合格			

69	GX-B1500/21-6-24003	2024/3/20	综合判定合格	 2024 03 05	
70	GX-B1500/21-6-24004	2024/3/20	综合判定合格	 2024 03 05	
71	GX-B1500/21-6-24005	2024/3/20	综合判定合格	 2024 03 05	

72	GX-B1500/21-6-24006	2024/3/20	综合判定合格		
73	GX-B1451/20-6-24036~24053	2024/3/20	所检项目合格		
74	GX-B1324/21-6-24006~24009	2024/3/20	所检项目合格		

75	GX-B1598/21-6-24017	2024/3/18	实测钢丝绳有效截面 积损失百分比最大为 4.27%，小于5%为正常。	
76	GX-B1598/21-6-24018	2024/3/18	实测钢丝绳有效截面 积损失百分比最大为 3.78%，小于5%为正常。	
77	GX-B1598/21-6-24019	2024/3/18	实测钢丝绳有效截面 积损失百分比最大为 3.80%，小于5%为正常。	

78	GX-B1598/21-6-24020	2024/3/18	实测钢丝绳有效截面积损失百分比最大为3.73%，小于5%为正常。	
79	GX-B1598/21-6-24021	2024/3/18	实测钢丝绳有效截面积损失百分比最大为3.25%，小于5%为正常。	
80	GX-B1598/21-6-24022	2024/3/18	实测钢丝绳有效截面积损失百分比最大为3.87%，小于5%为正常。	

81	GX-B1300/20-6-24002	2024/3/18	综合判定合格	
82	GX-B1520/20-6-24018	2024/3/18	综合判定合格	