

序号	报告编号	发布日期	结论	影像资料
139	GX-B1312/20-P-23044	2023年6月20日	所检项目合格。	
140	GX-B1312/20-P-23045~23047	2023年6月20日	本次共检电力变压器3台，3台电力变压器所检项目合格。	
141	GX-B1312/20-P-23048	2023年6月20日	所检项目合格。	

142	GX-B1312/20-P-23049	2023年6月20日	检项目合格。	
143	GX-B1417/22-P-23492	2023. 6. 27	综合判定：合格	
144	GX-B1417/22-P-23493	2023. 6. 27	综合判定：合格	

145	GX-B1417/22-P-23494	2023. 6. 27	综合判定：合格		
146	GX-B1417/22-P-23495	2023. 6. 27	综合判定：合格		
147	GX-B1339/21-P-23007	2023. 6. 27	所检项目合格		

148	GX-B1339/21-P-23008	2023. 6. 27	所检项目合格	 A worker wearing a yellow protective suit with reflective stripes and a red helmet is working in a dark environment. The worker is holding a tool or device. A timestamp '2023.6.8' is visible in the bottom right corner of the image.
149	GX-B1339/21-P-23009	2023. 6. 27	所检项目合格	 A worker wearing a yellow protective suit with reflective stripes and a red helmet is working in a dark environment. The worker is looking down at something. A timestamp '2023.6.8' is visible in the bottom right corner of the image.
150	GX-B1339/21-P-23010	2023. 6. 27	所检项目合格	 A worker wearing a yellow protective suit with reflective stripes and a red helmet is working in a dark environment. The worker is standing next to a piece of equipment. A timestamp '2023.6.8' is visible in the bottom right corner of the image.

151	GX-B1416/22-P-23048	2023年6月29日	综合判定：合格。 。		 2023 05 11	
152	GX-B1416/22-P-23049	2023年6月29日	综合判定：合格。 。		 2023 05 11	
153	GX-B1416/22-P-23050	2023年6月29日	综合判定：合格。 。		 2023 05 11	

154	GX-B1416/22-P-23051	2023年6月29日	综合判定：合格。 。	 <small>2023 05 11</small>	
155	GX-B1416/22-P-23052	2023年6月29日	综合判定：合格。 。	 <small>2023 05 23</small>	
156	GX-B1416/22-P-23053	2023年6月29日	综合判定：合格。 。	 <small>2023 05 23</small>	

157	GX-B1416/22-P-23054	2023年6月29日	综合判定：合格。 。	
158	GX-B1310/21-P-23035	2023. 6. 25	符合标准要求	
159	GX-B1321/20-P-23062~23063	2023. 6. 30	本次共检电力电缆2条，2条电力电缆所检项目合格。	

