

序号	报告编号	发布日期	结论	影像资料
7	GX-B1559/22-P-24177	2024. 11. 20	所检项目合格	
8	GX-B1559/22-P-24178	2024. 11. 20	所检项目合格	
9	GX-B1559/22-P-24175	2024. 11. 20	所检项目合格	

10	GX-B1559/22-P-24176	2024. 11. 20	所检项目合格	 A photograph showing two workers in safety gear (hard hats and work clothes) standing next to a yellow generator or power unit. The worker on the right is wearing a grey jacket and blue jeans, while the worker on the left is in a white uniform. The generator is yellow with black accents and has the number '22-08007' visible. The background shows a building with large white doors. A small timestamp '2024.11.8' is visible in the bottom right corner of the photo.
----	---------------------	--------------	--------	--

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

